

ULINE

TAPE GUIDE

WHICH TAPE SHOULD I USE?

FEATURE	Uline Industrial	Uline Economy	Uline Natural Rubber
Adhesion to Corrugated	Excellent	Good	Excellent
Application Temperature Range	0° – 140°F	50° – 110°F	0° – 150°F
Clarity	Excellent	Good	Good
Moisture Resistance	Very Good	Fair	Very Good


WHICH MIL SHOULD I USE?

CARTON WEIGHT	0"	20"	40"	60"	80"	100"
65-90 LBS.						3.5 MIL
50-65 LBS.					3.0 MIL	
35-50 LBS.				2.5-2.6 MIL		
15-35 LBS.			2.0 MIL			
0-15 LBS.		1.7-1.8 MIL				
	BOX LENGTH + WIDTH + HEIGHT					

HELPFUL HINTS

- Always seal boxes with one strip of tape.
- If you are using 2 strips of 2" tape, try a 3" tape or a thicker mil. This will save time and money.

2"	<ul style="list-style-type: none"> • For boxes 15" wide or less.
3"	<ul style="list-style-type: none"> • Boxes over 16" wide. • Underfilled RSC boxes. • Overstuffed boxes. • Difficult to adhere surfaces.



1-800-295-5510 uline.com